

Fault Report

Customer Name: <u>Johnstone</u>	Date: <u>21/2/24</u>
Customer Reference: <u>23784</u>	Fitter: <u>mc</u>
Salesperson: <u>SCOT</u>	Salesperson called: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Blind Type: <u>Vert Rail</u>	
Fault: <u>... Rail TOO SHORT ordered @ 1320</u> <u>SCOT measured customer as 1310</u>	
Action to correct: <u>new rail 1330 EXACT</u>	
Problem fixed on site: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
Further action required: YES <u>YES.</u>	