

# Fault Report

FITTER NAME: Michael	FITTING DATE: 1/14/24
Customer Name: Erin Summers Jersey	
Customer Ref: 23976.	
Salesperson: Stuart	Salesperson called: <input checked="" type="radio"/> Yes / <input type="radio"/> No
Blind Type and number:	
Problem fixed on site: Yes/No	
Fault Description One card snapped + other blind frayed.	
Action to Correct:-	