

Fault Report

Customer Name: <u>Robertson</u>	Date: <u>22/7/24</u>
Customer Reference: <u>24442</u>	Fitter: <u>MC</u>
Salesperson: <u>SCOT</u>	Salesperson called: <u>Yes/No</u>
<u>VISION</u>	
Fault Description: <u>measured @ 1417 x 1105</u> <u>needs to be</u>	
Action to correct: <u>1625 x 1190</u>	
Problem fixed on site: <u>Yes/No</u>	
Further action required: <u>Yes</u>	