

Fault Report

Customer Name <i>ms Sheriff</i>	Date; <i>15/11/24</i>
Customer Reference: <i>24665</i>	Fitter <i>michael.</i>
Salesperson: <i>Scot</i>	Salesperson called: Yes/No
Fault Description: <i>chain has come off roller blind.</i>	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required:	