

# Fault Report

Customer Name : <i>Menderson</i>	Date: <i>6/8/24</i>
Customer Reference: <i>24560 <del>177</del></i>	Fitter: <i>Michael</i>
Salesperson: <i>SCOT</i>	Salesperson called: Yes/ <input checked="" type="radio"/> No
Blind Type: <i>wooden, 1</i>	
Fault Description: <i>MIS MEASURE. Old: 2355 x 1403 New: 2365 x 1445.</i>	
Action to correct: <i>Re. order</i>	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required: <i>YES</i> <i>YES.</i>	