

# Fault Report

Customer Name <i>T Watson</i>	Date; <i>20/12/24</i>
Customer Reference: <i>24723</i>	Fitter <i>michael</i>
Salesperson:	Salesperson called: Yes/No
Fault Description: <i>Stopper at top of shutter falling out.</i>	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required:	