

Fault Report

Customer Name MCKAY	Date: 16/8/24
Customer Reference: 24627	Fitter: MICHAEL
Salesperson: SCOT	Salesperson called: Yes/No <input checked="" type="radio"/>
Blind Type: Roller	
Fault Description: MIS MEASURE Old: 1450x1170 NEW: 12137x1170	
Action to correct: Re order	
Problem fixed on site: Yes/No <input checked="" type="radio"/>	
Further action required: YES	