

Fault Report

Customer Name Brenda Gerie	Date; now 11/11/24 6/11/24
Customer Reference: 24603	Fitter michael.
Salesperson:	Salesperson called: Yes/No
Fault Description: String broken top of window at right had side cord blind sitting tilted.	
Action to correct: Cord had come out of the clip in headrail -recorded	
Problem fixed on site: Yes/No	
Further action required: NO	