

Fri 20/12.

Fault Report

Customer Name: MECALLUM	Date: 10/12/24
Customer Reference: 25119	Fitter: COLIN
Salesperson: STUART	Salesperson called: Yes /No
Blind Type and number: 2 x P/FIT VENETIAN	
Fault Description: CUT OUTS NOT TAKING OUT OF FRAMES.	
Action to correct: SENT BACK TO FACTORY FOR REPAIR.	
Problem fixed on site: Yes /No	
Further action required: Yes.	

CUT OUTS
WRONG SIDES
OF
FRAMES!