

# Fault Report

Customer Name mclenan	Date; 6/1/25
Customer Reference: 25246	Fitter Stuart
Salesperson: Stuart	Salesperson called: Yes/No
Fault Description: Too much tension	
Action to correct: Release some tension	
Problem fixed on site: <del>Yes/No</del>	
Further action required: NO	