

Fault Report

Customer Name Ikechuku	Date; 17/12/24
Customer Reference: 25038	Fitter Stuart
Salesperson: Stuart	Salesperson called: Yes/No --
Fault Description: retension blind.	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required:	