

mor 6/11.

Fault Report

Customer Name Wolthepoon	Date:
Customer Reference: 24983	Fitter Colin
Salesperson:	Salesperson called: Yes/No
Fault Description: See photos	
Action to correct: new components ordered	
Problem fixed on site: Yes <input checked="" type="radio"/> No <input type="radio"/>	
Further action required:	

24185 waterpact



