

# Fault Report

Customer Name GUYAN	Date; 12/12/24
Customer Reference: 24943	Fitter MICHAEL
Salesperson: STUART	Salesperson called: Yes/ <input checked="" type="radio"/> No
Fault Description: 1x blind to big	
Action to correct: Remake @ 2080 x 1772 Recess	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required: Yes	