

3011

Fault Report

Customer Name MAIR	Date; 21/01/25
Customer Reference: 25294	Fitter MICHAEL
Salesperson: DAVID	Salesperson called: Yes/No <input checked="" type="radio"/>
Fault Description: should be P/fit plate in soft Pewter Fresco B/O not ven in 1235	
Action to correct: Remake as a plate	
Problem fixed on site: Yes/No <input checked="" type="radio"/>	
Further action required: yes	