

Fault Report

Customer Name MCLAREN	Date; 13/03/25
Customer Reference: 25451	Fitter MILHAEL
Salesperson: STUART	Salesperson called: Yes/ <input checked="" type="radio"/> No
Fault Description: 1 x BLIND (BLIND 5 1708 x 1204) TOO WIDE NEEDS CUT DOWN TO W/660 mm 1 x BLIND (BLIND 3 1358 x 1604) SHOULD BE 1064 DROP	
Action to correct: SEE ABOVE	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required: YES SEE ABOVE	