

# Fault Report

Customer Name Ingram	Date; 6/2/25
Customer Reference: 25161.	Fitter Stuart
Salesperson: Stuart	Salesperson called: Yes/No " "
Fault Description: 2x perfect Rits, TOPs were hanging off and broke off when taking off.	
Action to correct: need re attached at top	
Problem fixed on site: Yes/No <input checked="" type="radio"/> No	
Further action required:	