

Fault Report

Customer Name JOHNSTONE	Date; 07/03/25
Customer Reference: 25482	Fitter MICHAEL
Salesperson: MICHAEL	Salesperson called: <input checked="" type="radio"/> Yes / <input type="radio"/> No
Fault Description: MISSMEASURE SHOULD BE 370 NOT 670	
Action to correct: Per Cut down to 370	
Problem fixed on site: Yes / <input checked="" type="radio"/> No	
Further action required: YES	