

# Fault Report

Customer Name Little	Date;
Customer Reference: 2SS11	Fitter Michael
Salesperson: Stuart	Salesperson called: Yes/No

## Fault Description:

Scratch on bottom bar on blind  
NO 2 (1420)

## Action to correct:

REPLACE BOTTOM BAR ON BLIND NO  
2

Problem fixed on site: Yes/No

## Further action required:

YES, RETURN TO FIT NEW BOTTOM  
BAR.