

Fault Report

Customer Name COOPER	Date; 07/03/25
Customer Reference: 25510	Fitter MICHAEL
Salesperson: XXXXXXXXXX SARAH	Salesperson called: Yes/ <input checked="" type="radio"/> No
Fault Description: NO HOLES IN FRAME FOR BRACKETS	
Action to correct: PUNCH HOLES FOR BRACKETS	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required: YES PUNCH HOLES FOR BRACKETS AND GO TO FIT	