

Fault Report

Customer Name McLean	Date; 10/04/25
Customer Reference: 25580	Fitter MICHAEL
Salesperson: LEWIS.	Salesperson called: Yes <input checked="" type="radio"/> No
Fault Description: MISSMEASURE	
Action to correct: REMAKE BLIND AS 1795 x 1021 Recess Pelmet size - 1818 Fitting Height - 2350	
Problem fixed on site: Yes <input checked="" type="radio"/> No	
Further action required: YES, REMAKE AND RETURN TO FIT	