

Fault Report

Customer Name MARNIE	Date; 04/04/25
Customer Reference: 25591	Fitter MICHAEL
Salesperson: LEWIS	Salesperson called: Yes/ <input checked="" type="radio"/> No

Fault Description:

BLIND NO 3,4,5 HAVE BEEN MEASURED AS SIZE OF WINDOW SILL INSTEAD OF SIZE OF FACING SO IF FITTED BLINDS WOULD JUST RUB AGAINST WINDOW SURROUND

Action to correct:

REMAKE / CUT DOWN TO: (ALL RECESS)
3 - 1110 MM
4 - 1592 MM
5 1127 MM

Problem fixed on site: Yes/No

Further action required:

YES CUT BLINDS DOWN AND RETURN TO FIT