

Fault Report

Customer Name SMITH	Date; 18/03/25
Customer Reference: 25518	Fitter MICHAEL
Salesperson: STUART	Salesperson called: Yes/ <input checked="" type="radio"/> No
Fault Description: Blind NO 1 TOO BIG, HITTING SKIRTING	
Action to correct: Remake Blind or cut down to 1115 recess	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required: YES, Remake or cut down blind and return to fit.	