

Fault Report

Customer Name Lauren Honey	Date; 24/03/25
Customer Reference: 25644	Fitter Michael
Salesperson: Lewis	Salesperson called: <u>Yes</u> / No

Fault Description:

Not Blackout and to be made blackout

Action to correct:

Re-make ~~Blin~~ Roman with B/O Linings

Problem fixed on site: Yes/~~No~~

Further action required:

