

# Fault Report

Customer Name MARNIE	Date; 04/04/25
Customer Reference: 25591	Fitter MICHAEL
Salesperson: LEWIS	Salesperson called: Yes <input checked="" type="radio"/> No
Fault Description: BLIND NO 3,4,5 HAVE BEEN MEASURED AS SIZE OF WINDOW SILL INSTEAD OF SIZE OF FACING SO IF FITTED BLINDS WOULD JUST RUB AGAINST WINDOW SURROUND	
Action to correct: REMAKE / CUT DOWN TO: (ALL RECESS) 3 - 1110 MM 4 - 1592 MM 5 1127 MM	
Problem fixed on site: Yes <input checked="" type="radio"/> No	
Further action required: YES CUT BLINDS DOWN AND RETURN TO FIT	