

Fault Report

Customer Name Ian Wright	Date; 21/4/25
Customer Reference: OS19	Fitter Michael
Salesperson: Lewis	Salesperson called: Yes/No

Fault Description:

Roller blind crinkled at bottom

Action to correct:

Return to factory for repair

Problem fixed on site: Yes/No

Further action required: