

Fault Report

Customer Name COLLINSON	Date; 22/04/25
Customer Reference: 25670	Fitter MICHAEL
Salesperson: LEWIS	Salesperson called: Yes/ <input checked="" type="radio"/> No

Fault Description:

BLIND SHOULD BE 1550 RECESS
NOT 1550 FABRIC WIDTH

Action to correct:

CUT DOWN TO 1550 RECESS

Problem fixed on site: Yes/No

Further action required:

YES, CUT DOWN AND RETURN TO FIT