

Fault Report

Customer Name Phillips	Date: 01/05/25
Customer Reference: 25475	Fitter michael
Salesperson: michael	Salesperson called: Yes/No

Fault Description:

See email piche - slot coming away at top - manufacturing error

Action to correct:

remove slot then refit.

Problem fixed on site: Yes/No

Further action required: