

S


From: George Ralph <george.ralph@btinternet.com>
Sent: 20 May 2025 17:27
To: Enquiries
Subject: Ralph Alford Shower Room Blind Repair

Follow Up Flag: Follow up
Flag Status: Completed

Please find attached close up photo of the cord failure point, not it is not associated with the child safety attachment

ESS - needs to be returned to factory.

Refer to sales order 21780



Kind regards,

George Ralph

George.ralph@btinternet.com

07734 910 126

Sent from my iPhone