

Fault Report

Customer Name HENDERSON	Date; 24/05/25
Customer Reference: 25748	Fitter MICHAEL
Salesperson: LEWIS	Salesperson called: Yes/ <input checked="" type="radio"/> No
Fault Description: Perfect fits Running off	
Action to correct: Steven says need changed to chain control 1x Left 1x Right.	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required: Yes, change to chain control and return to fit.	