

# Fault Report

Customer Name BUCHAN	Date; 06/08/25
Customer Reference: 26052	Fitter MICHAEL
Salesperson: LEWIS	Salesperson called: Yes/No <input checked="" type="radio"/> No
Fault Description: Blind NO 2 too big should be 990 Recess	
Action to correct: Cut down to 990 Recess	
Problem fixed on site: Yes/No <input checked="" type="radio"/> No	
Further action required: Yes, cut down & return to fit ASAP	