

# Fault Report

Customer Name <i>milne High</i>	Date; <i>14/8/25</i>
Customer Reference: <i>GBC 064</i>	Fitter
Salesperson:	Salesperson called: Yes/No
Fault Description: <i>blind omitted from order.</i>	
Action to correct: <i>Order unit + b16 Granite 1109 width, 1900 drop 2300 fitting height metal continuous chain</i>	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required:	