

Fault Report

Customer Name Helen Grey	Date; 15/08/25
Customer Reference:	Fitter Michael
Salesperson: Lewis	Salesperson called: <input checked="" type="radio"/> Yes/ <input type="radio"/> No
Fault Description: No Fault	
Action to correct: Roller Being used in New Perfect	
Problem fixed on site: <input checked="" type="radio"/> Yes/ <input type="radio"/> No	
Further action required: Fabric to be reused in new perfect fit systems	