

Fault Report

Customer Name Breese	Date; 27/8/25
Customer Reference: ZS618	Fitter Michael.
Salesperson: HE STEVEN	Salesperson called: Yes/No
Fault Description: Cover strips falling off	
Action to correct: added caulk behind cover strips	
Problem fixed on site: Yes/No	
Further action required: No.	