

Fault Report

Customer Name <i>Coutts</i>	Date; <i>05/09/25</i>
Customer Reference: <i>26118</i>	Fitter <i>Michael</i>
Salesperson: <i>Lewis</i>	Salesperson called: Yes/No
Fault Description: <i>Roller blind (1471w + 1124d) should have had a black headbox</i>	
Action to correct: <i>Send roller back to factory to have black headbox fitted.</i>	
Problem fixed on site: Yes /No	
Further action required:	