

Fault Report

Customer Name <i>morrison</i>	Date; <i>09/09/25</i>
Customer Reference: <i>25367</i>	Fitter: <i>michael</i>
Salesperson:	Salesperson called: Yes/No
Fault Description: <i>adhesive strips coming away on shutters.</i>	
Action to correct: <i>replace adhesive strips</i>	
Problem fixed on site: <u>Yes</u> /No	
Further action required:	