

# Fault Report

Customer Name Toot	Date; 22/08/25
Customer Reference: 0585	Fitter Michael
Salesperson: Lewis	Salesperson called: <input checked="" type="radio"/> Yes / <input type="radio"/> No
Fault Description:  Fabric cover not stuck down properly	
Action to correct:  Re-Glue Fabric insert	
Problem fixed on site: <input checked="" type="radio"/> Yes / <input type="radio"/> No	
Further action required:  Factory to Re-stick Fabric insert	