

Fault Report

Customer Name SMITH	Date; 06/10/25
Customer Reference: 26347	Fitter MICHAEL
Salesperson: SHOP	Salesperson called: Yes/ <input checked="" type="radio"/> No
Fault Description: 1 x blind supplied as SK06 instead of 306 so its too big	
Action to correct: Reorder 306	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required: Yes, reorder & return to fit.	