

# Fault Report

Customer Name MACIS	Date; 07/10/25
Customer Reference: 26209	Fitter MICHAEL
Salesperson: LEWIS	Salesperson called: Yes/ <input checked="" type="radio"/> No
Fault Description: Blind nos too big	
Action to correct: cut down to 1280 Recess	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required: cut down & return to fit ASAP	