

Fault Report

Customer <i>CENTURION</i>	
Customer no <i>GBC 095</i>	Fitter <i>AMO</i>
Salesperson	Salesperson called:
Fault Description: <i>BLIND 100 BIG 40mm</i>	
Action to correct - <i>NEED TO CUT DOWN</i>	
Problem fixed on site: <i>NO</i>	