

Fault Report

Customer Name Duff	Date; 30/10/2025
Customer Reference: 26330	Fitter Michael
Salesperson: Lewis	Salesperson called: <input checked="" type="radio"/> Yes/ <input type="radio"/> No
Fault Description: Blind ① has multiple creases	
Action to correct: Blind ① needs ironed / decreased	
Problem fixed on site: <input checked="" type="radio"/> Yes/ <input type="radio"/> No	
Further action required: send blind ① to factory to sort creasing	