

# Fault Report

Customer Name <b>RENNIE</b>	Date: <b>02/12/25</b>
Customer Reference: <b>26389</b>	Fitter <b>MICHAEL</b>
Salesperson: <b>LEWIS</b>	Salesperson called: Yes/No
Fault Description: <b>MISSMEASURE BLIND NO <del>10</del> 11</b>	
Action to correct: <b>Cut down to 1828 Recess</b>	
Problem fixed on site: Yes <input checked="" type="radio"/> No <input type="radio"/>	
Further action required: <b>YES, cut down &amp; return to fit</b>	