

Fault Report

Customer Name Hird	Date: 16/12/25.
Customer Reference: 26530	Fitter
Salesperson: MICHAEL	Salesperson called: Yes/No
Fault Description: Blinds not made to headbox Size	
Action to correct: Fit roller to existing tubes	
Problem fixed on site: Yes <input checked="" type="radio"/> No	
Further action required: yes fit roll to existing head boxes & tubes	