

# Fault Report

Customer Name <i>Smith</i>	Date: <i>13/01/26</i>
Customer Reference: <i>26721</i>	Fitter <i>Michael</i>
Salesperson: <i>Greg</i>	Salesperson called: Yes/No
Fault Description: <i>fabric pattern should run horizontal same as the blind</i>	
Action to correct: <i>replace fabric for inset</i>	
Problem fixed on site: <del>Yes</del> /No	
Further action required: <i>reorder fabric and return to fit.</i>	