

Fault Report

Customer Name THOMSON	Date: 09/02/26
Customer Reference: 26887	Fitter MICHAEL
Salesperson: KEVIN	Salesperson called: <input checked="" type="radio"/> Yes/ <input type="radio"/> No
Fault Description: Blind NO2 too big	
Action to correct: Cut down / remake @ 1735 Recess	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required: Yes remake / cut down & return to fit -	