

Fault Report

Customer Name GORDON	Date: 24/02/26
Customer Reference: 26897	Fitter MICHAEL
Salesperson: Kevin	Salesperson called: Yes/No
Fault Description: Blind NOS Drop too long	
Action to correct: Cut down <u>drop</u> to 1180mm	
Problem fixed on site: Yes <input checked="" type="radio"/> No	
Further action required: Yes cut down drop & return to fit.	