

Fault Report

Customer Name <i>Ann Corp</i>	Date; <i>10/3/26</i>
Customer Reference: <i>GBC113</i>	Fitter <i>Amo</i>
Salesperson: <i>Steven</i>	Salesperson called: Yes/No
Fault Description: <i>continuous chain on blind 3 too long should be 1000</i>	
Action to correct: <i>cut chain down to 1000</i>	
Problem fixed on site: Yes /No	
Further action required: <i>return to site and cut chain down to 1000</i>	