

Fault Report

Customer Name Forbes	Date; 17/3/26
Customer Reference: L244	Fitter Michael
Salesperson: Kevin	Salesperson called: Yes /No
Fault Description: Blind 1+4 edges are frayed (Gizeme has pics).	
Action to correct: remake blind 1+4	
Problem fixed on site: Yes /No	
Further action required: remake blind 1+4 and return to fit	