

Fault Report

Customer Name COOPER	Date; 30/3/26
Customer Reference: 27033	Fitter MICHAEL
Salesperson: KEVIN	Salesperson called: Yes/No
Fault Description: Living Room (R) ordered as RL L4 instead of RL	
Action to correct: Reorder blind with RL controls RL	
Problem fixed on site: Yes/No	
Further action required: Yes, reorder & return to fit.	