

Fault Report

Customer Name MORRISON	Date; 06/04/26
Customer Reference: 27103	Fitter MICHAEL
Salesperson: KEVIN	Salesperson called: Yes/No
Fault Description: WINDOW (R) Blind no 3 too big seems as if measured at sill	
Action to correct: Cut blind down to 1810 mm Recess	
Problem fixed on site: Yes/No <input checked="" type="checkbox"/> No	
Further action required: Cut down & return to fit.	