

# Fault Report

Customer Name <i>MARSELLA</i>	Date: <i>01/4/26</i>
Customer Reference: <i>26818</i>	Fitter <i>MICHAEL</i>
Salesperson: <i>KEVIN</i>	Salesperson called: Yes/ <del>No</del>
Fault Description: • INCREASE LIVING ROOM BLIND BY 35mm (2055 PROP) (SPLIT) • INCREASE DROP OF BEDROOM BLIND TO 1155mm (GOING TO RIGHT (NOT SPLIT)) • RIGHT ENDSLAT HITS THE CHAIN CUP / WONT CLOSE.	
Action to correct: <i>REMAKE BLINDS</i>	
Problem fixed on site: <del>Yes</del> /No	
Further action required: <i>REMAKE BLINDS</i>	